

PREVIEW RO# I 57559 CUST# 10000 STARR AG 5130 COMBINE TRADE
UNIT# 46293 2012 CASE-IH 5130 COMBINE

***** REPAIR ORDER SUMMARY DATA *****
STARR AG 5130 COMBINE TRADE CUST# 10000 RO# I57559
START 2/02/16 16:58
BILLED 3/09/16 16:16
PILOT GROVE IA 52648-0000 PO#
PHONE: HOME 319 469-4461 PHC 12 PBC 04 WRITER 024
APPROVAL 024 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 7 W PRB 0
BILLED 3/09/16 16:16 050 BILLED
LABOR 0.00 918.59 0.00
PARTS 0.00 2,111.63 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 9.19 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 3,039.41 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46293 2012 CASE-IH 5130 COMBI CURR HRS 775.0
DELIVERED: 3/31/14
VIN: YCG008182
TIRE SIZE: 470/70R30 W/MDH AXLE SN: 30.5X32
FEEDER LENGTH: AMFMWB CUT TYPE: BLKHTR
ROTOR HRS: 577HR 11-20-14
WARRANTY EFF: 9/01/12 EXT: N UNIT: YCG008182 EXP: 8/31/13
ENG: 4HF000977953 EXP: 8/31/14

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CPO INSPECTION
TAKE SAMPLES OF:
ENGINE OIL, COOLANT, HYDRAULIC RESERVOIR AND PTO GEARBOX
CORRECTION: RUN COMBINE
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
172 .95 61.50 58.43
172 1.47 61.50 90.41
172 2.68 61.50 164.82
172 1.17 61.50 71.96
PARTS: SG4PACK OIL ANALYS 1.00 124.35 124.35
UPS OUT 1.00 8.66 8.66
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
385.62 133.01 0.00 0.00 0.00 518.63

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: FIX LIGHTS, RIGHT FRONT FLASHER
INSTALL BEACON ON FRONT RIGHT
ADJUST RIGHT REAR PANEL LATCH
SEAL HOLE ON RIGHT SIDE OF CAB
CORRECTION: INSTALLED NEW BULB.
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
172 .35 63.75 22.31
172 1.13 63.75 72.04
PARTS: 529068 BULB / 115 1.00 2.70 2.70
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
94.35 2.70 0.00 0.00 0.00 97.05

***** PROBLEM # 03 DETAILS *****

PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: ROTARY AIR SCREEN ANGLE IRON IS CRACKED, REPAIR
REPAIR SPREADER PAN
INSTALL MISSING BOLTS IN SPREADER CONES
SPREADER BELT NOT ON RIGHT PULLEYS, REPAIR

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			.30	63.75	19.13
	172			1.35	63.75	86.06
PARTS:	P2707-581		5/16 X 3/4	7.00	.27	1.89
	145458		WHIZ NUT /	7.00	.58	4.06
3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	105.19	5.95	0.00	0.00	0.00	111.14

***** PROBLEM # 04 DETAILS *****

PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: TRANSMISSION IS LOW
RESERVOIR IS LOW
ROTOR GEAR BOX IS LOW
INCLINED GEAR BOX IS LOW
CORRECTION: ADDED HYTRAN TO TRANSMISSION, RESERVOIR, ROTOR GEAR BOX AND
INCLINED GEAR BOX.

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			.25	63.75	15.94
	172			.43	63.75	27.41
PARTS:	HYTRAN		OIL / 1 GA	2.12	14.89	31.57
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	43.35	31.57	0.00	0.00	0.00	74.92

***** PROBLEM # 05 DETAILS *****

PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: FIX OIL LEAK BY IN LINE FILTER
FIX OIL LEAK BY SIGHT GLASS ON TWO SPEED FEEDER GEAR BOX
FEEDER DRIVE GEAR BOX IS LOW

CORRECTION: INSTALLED NEW CENTER GEARBOX SIGHT GLASS

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			.25	63.75	15.94
	172			.30	63.75	19.13
PARTS:	87524452		SIGHTGLASS	1.00	16.25	16.25
	W10077		11OZ CLEAN	2.00	2.45	4.90
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	35.07	21.15	0.00	0.00	0.00	56.22

***** PROBLEM # 06 DETAILS *****

PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: REPLACED BATTERIES
CHANGED RECIRCULATION FILTER
REPLACED FILLER PLATE ON CHOPPER PAN
REPLACED FRONT HALF RASP BARS ON ROTOR

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			1.30	63.75	82.88
	172			1.23	63.75	78.41
PARTS:	BMF31GW		BATTERY	2.00	125.00	250.00
	BMF31GW		(CORE CHA			0.00
	BMF31GW		(CORE CRE			0.00
	120486A2		FILTER / C	1.00	34.75	34.75
	B95365		1/2 KIT /	1.00	865.00	865.00
	P2838-201		BOLT / M12	50.00	.80	40.00
	84551013		COVER, CHO	1.00	84.50	84.50
6	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	161.29	1274.25	0.00	0.00	0.00	1435.54

PROBLEM # 07 DETAILS

PRB# 7 LABOR TYPE 1I INTERNAL WORK
COMPLAINT: REPLACED ROCK TRAP DRIVE CHAIN
REPLACED UNLOADING DRIVE CHAIN
REPLACED TAILINGS DRIVE CHAIN
REPLACED CLEAN GRAIN DRIVE CHAIN

** BILLED **

HOLD STATUS: F FINISHED
OPR# 1

SKILL LEVEL:

TECH #: 172

	172			.18	63.75	11.48
	172			1.29	63.75	82.24
PARTS:	47667739	CHAIN ROCK	1.00	170.00	170.00	
	87707588	CHAIN, UNL	1.00	159.00	159.00	
	84164207	CHAIN, TA	1.00	137.00	137.00	
	84163936	CHAIN, CLE	1.00	177.00	177.00	
7	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	93.72	643.00	0.00	0.00	0.00	736.72

REPAIR ORDER TOTALS

LABOR SALE	918.59
PARTS SALE	2,111.63
REPAIR ORDER SUBTOTAL	3,030.22
TOTAL MISC. SHOP SUPPLIES	9.19
TOTAL DUE	3,039.41

PREVIEW RO# I 57519 CUST# 10000 STARR AG 5130 COMBINE TRADE
 UNIT# 46293 2012 CASE-IH 5130 COMBINE

***** REPAIR ORDER SUMMARY DATA *****
 STARR AG 5130 COMBINE TRADE CUST# 10000 RO# I57519
 START 1/26/16 11:07
 BILLED 3/09/16 16:12
 PILOT GROVE IA 52648-0000 PO#
 WRITER 050
 PHONE: HOME 319 469-4461 PHC 10 PBC 05 APPROVAL 050 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
 C PRB 0 I PRB 3 W PRB 0
 BILLED BILLED 3/09/16 16:12 050 BILLED
 LABOR 0.00 1,099.28 0.00
 PARTS 0.00 1,002.29 0.00
 SUBLET 0.00 0.00 0.00
 OTHER 0.00 0.00 0.00
 MISC EXP 0.00 0.00 0.00
 MISC CHARGES 0.00 6.07 0.00
 DEDUCTIBLE 0.00 0.00 0.00
 TAX 0.00 0.00 0.00
 TOTAL DUE 0.00 2,107.64 0.00

***** SERVICE UNIT INFORMATION *****
 OWNER 10000 UNIT# 46293 2012 CASE-IH 5130 COMBI CURR HRS 775.0
 DELIVERED: 3/31/14
 VIN: YCG008182
 TIRE SIZE: 470/70R30 W/MDH AXLE SN: 30.5X32
 FEEDER LENGTH: AMFMWB CUT TYPE: BLKHTR
 ROTOR HRS: 577HR 11-20-14
 WARRANTY EFF: 9/01/12 EXT: N UNIT: YCG008182 EXP: 8/31/13
 ENG: 4HF000977953 EXP: 8/31/14

***** PROBLEM # 01 DETAILS *****
 PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING SERVICE
 MIKE AND PHIL ARE DOING PROBLEMS OFF OF CPO
 PERFORM THE STEPS OUTLINED ON THE FORM TITLED "COMBINE
 SERVICING CHECK LIST FOR MID-RANGE COMBINES"
 CORRECTION: CHANGED INNER AND OUTER AIR FILTERS, CHANGED HYD FILTER,
 CHANGED CAB AIR AND CAB RECIRCULATION FILTERS. CHANGED FUEL
 SEPARATOR FILTER, CHANGED OIL FILTER AND OIL.
 HOLD STATUS: F FINISHED
 OPR# 1 I.COMSEMIRSC00 ----- FLAT RATE SKILL LEVEL:
 INT. COMBINE (MID-RANGE)-RECONDITIONING SER
 TECH #: 225
 026 2.06 0.00
 026 2.14 0.00
 026 1.55 0.00
 026 1.75 0.00
 221 1.33 0.00
 221 1.90 0.00
 225 1.38 0.00
 225 2.63 0.00
 225 1.30 0.00
 LABOR: 6.00 82.00 492.00
 PARTS: 73341702 5 GALLON / 1.00 78.50 78.50
 86998333 AIR FILTER 1.00 106.00 106.00
 86998332 AIR FILTER 1.00 80.50 80.50
 1329214C1 HYDRAULIC 1.00 137.00 137.00
 120486A2 FILTER / C 1.00 34.75 34.75
 84217229 FILTER / C 1.00 51.00 51.00
 84228488 OIL FILTER 1.00 23.00 23.00
 84412164 FILTER, PR 1.00 26.50 26.50
 84348882 CARTRIDGE, 1.00 28.00 28.00
 HYTRANC 1 GAL / HY 15.00 14.89 223.35
 1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 492.00 788.60 0.00 0.00 0.00 1280.60

***** PROBLEM # 02 DETAILS *****

PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: CODY ASSISTED MIKE WALKER ON FIXING THE AIR SCREEN 2-18-16
 HOLD STATUS: F FINISHED
 OPR# 1

SKILL LEVEL:

TECH #: 026

	139				1.00	61.50	61.50
	225				2.87	61.50	176.51
2	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	238.01	0.00	0.00	0.00		0.00	238.01

***** PROBLEM # 03 DETAILS *****

PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: CHANGE PTO GEARBOX OIL
 DRAIN HYDRAULIC RESERVOIR AND RE-FILL
 CHANGE COOLANT FLUID
 CHANGE PTO OIL

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 026

	221				.48	51.75	24.84
	221				2.52	51.75	130.41
	225				1.18	61.50	72.57
	225				2.30	61.50	141.45
PARTS:	B30205			ANTIFREEZE	4.00	33.88	135.52
	HYTRAN			OIL / 1 GA	5.25	14.89	78.17
3	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	369.27	213.69	0.00	0.00		0.00	582.96

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,099.28
PARTS SALE	1,002.29
REPAIR ORDER SUBTOTAL	2,101.57
TOTAL MISC. SHOP SUPPLIES	6.07
TOTAL DUE	2,107.64