

PREVIEW RO# I 57561 CUST# 10000 MIKE FRAZIER 7130 COMB TRADE  
UNIT# 46268 2012 CASE-IH 7130

\*\*\*\*\* REPAIR ORDER SUMMARY DATA \*\*\*\*\*  
MIKE FRAZIER 7130 COMB TRADE CUST# 10000 RO# I57561  
START 2/03/16 08:01  
BILLED 2/18/16 16:48  
PILOT GROVE IA 52648-0000 PO#  
WRITER 050  
PHONE: HOME 319 469-4461 PHC 15 PBC 01 APPROVAL 050 /050

\*\*\*\*\* REPAIR ORDER TOTALS BY PAY TYPE \*\*\*\*\*  
C PRB 0 I PRB 5 W PRB 0  
BILLED BILLED 2/18/16 16:48 050 BILLED  
LABOR 0.00 2,550.53 0.00  
PARTS 0.00 887.45 0.00  
SUBLET 0.00 0.00 0.00  
OTHER 0.00 0.00 0.00  
MISC EXP 0.00 0.00 0.00  
MISC CHARGES 0.00 20.59 0.00  
DEDUCTIBLE 0.00 0.00 0.00  
TAX 0.00 0.00 0.00  
TOTAL DUE 0.00 3,458.57 0.00

\*\*\*\*\* SERVICE UNIT INFORMATION \*\*\*\*\*  
OWNER 10000 UNIT# 46268 2012 CASE-IH 7130 CURR HRS 697.0  
DELIVERED: 12/20/13  
VIN: YCG007497  
TIRE SIZE: 900/60/30 RK TR AXLE SN: 2-CAMERAS 7/13  
FEEDER LENGTH: BLKHTR CUT TYPE: AMFMWB  
ROTOR HRS: 531 HR 2-18-16  
WARRANTY EFF: 9/01/12 EXT: N UNIT: YCG007497 EXP: 8/31/13  
ENG: 2CF020021617 EXP: 8/31/14

\*\*\*\*\* PROBLEM # 01 DETAILS \*\*\*\*\*  
PRB# 1 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*  
COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING SERVICE  
PHIL IS DOING SOME OF THE PROBLEMS ON CPO INSPECTION  
CORRECTION: PERFORM THE STEPS OUTLINED ON THE FORM TITLED "COMBINE  
SERVICING CHECK LIST FOR MID-RANGE COMBINES"  
\*\*NEED TO CHANGE THE OIL IN THE PTO GEARBOX\*\*

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 228

172	.15	61.50	9.23
172	.27	61.50	16.61
228	.83	61.50	51.05
228	1.20	61.50	73.80
228	1.38	61.50	84.87
228	.45	61.50	27.68
228	2.47	61.50	151.91
228	1.33	61.50	81.80
228	2.73	61.50	167.90
228	1.72	61.50	105.78
228	1.72	61.50	105.78

OPR# 2 I.COMSEMIRSC00 ----- FLAT RATE SKILL LEVEL:

INT. COMBINE (MID-RANGE)-RECONDITIONING SER

TECH #: 228

228	.53		0.00
LABOR:	6.00	82.00	492.00
PARTS:	1329214C1	HYDRAULIC	1.00 137.00 137.00
	87684758	FILTER, IN	1.00 38.00 38.00
	84346773	OIL FILTER	1.00 54.75 54.75
	84597064	FILTER, FU	1.00 45.00 45.00
	86998333	AIR FILTER	1.00 106.00 106.00
	86998332	AIR FILTER	1.00 80.50 80.50
	15W40D	1 GALLON /	6.50 14.75 95.88
	HYTRAN	OIL / 1 GA	14.75 14.89 219.63
	84217229	FILTER / C	1.00 51.00 51.00
	120486A2	FILTER / C	1.00 34.75 34.75

	15W40D		1 GALLON /	1.00	14.75	14.75
	120512HX		BATTERY BO	1.00	1.41	1.41
1	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	1368.41	878.67	0.00	0.00	0.00	2247.08

\*\*\*\*\* PROBLEM # 02 DETAILS \*\*\*\*\*

PRB# 2 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: WELD BROKEN WELD ON AIR SCREEN  
 ADJUST FEEDER CHAIN, TIGHTEN  
 STRAIGHTEN SPREADER TRAY

CORRECTION: ADJUSTED FEEDER CHAIN, SECURED SPREADER TRAY.  
 REPLACED BATTERY TERMINAL BOLT, FIXED AIR SCREEN BY WELDING.

HOLD STATUS: F FINISHED  
 OPR# 1 SKILL LEVEL:

TECH #: 228

	228			1.57	61.50	96.56
	228			.25	71.25	17.81
2	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	114.37	0.00	0.00	0.00	0.00	114.37

\*\*\*\*\* PROBLEM # 03 DETAILS \*\*\*\*\*

PRB# 3 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: INSTALL MISSING NUT ON ROCK TRAP MOUNT  
 INSTALL MISSING BOLT ROCK TRAP, TOP AND BOTTOM  
 TIGHTEN FEEDER FACE PLATE MOUNT BOLTS

CORRECTION: REPLACED MISSING NUTS AND BOLTS ON ROCK TRAP. TIGHTENED  
 FEEDER FACE PLATE.

HOLD STATUS: F FINISHED  
 OPR# 1 SKILL LEVEL:

TECH #: 228

	228			1.40	61.50	86.10
PARTS:	87681210		8MM NUT /	1.00	.86	0.86
	43435		NUT, M10 -	2.00	.68	1.36
	614-10050		10MM X 50M	1.00	1.92	1.92
	140045		WASHER / 1	6.00	.54	3.24
	86508618		BOLT, M10X	1.00	1.40	1.40
3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	86.10	8.78	0.00	0.00	0.00	94.88

\*\*\*\*\* PROBLEM # 04 DETAILS \*\*\*\*\*

PRB# 4 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: DO SOME OTHER WORK  
 PHILLIP IS HELPING JOSH WITH CPO INSPECTION  
 GERMAIN WAS HELPING JOSH WITH CPO INSPECTION

HOLD STATUS: F FINISHED  
 OPR# 1 SKILL LEVEL:

TECH #: 228

	139			1.23	61.50	75.65
	174			.24	61.50	14.76
	228			.88	61.50	54.12
	228			1.63	61.50	100.25
	228			.58	61.50	35.67
	228			1.45	61.50	89.18
	228			2.55	61.50	156.83
	228			2.68	61.50	164.82
	228			1.65	61.50	101.48
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	792.76	0.00	0.00	0.00	0.00	792.76

\*\*\*\*\* PROBLEM # 05 DETAILS \*\*\*\*\*

PRB# 5 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: CLEAN AND DETAIL

CORRECTION: CODI CLEANED 2-18-16

HOLD STATUS: F FINISHED  
 OPR# 1 SKILL LEVEL:

TECH #: 228

	149			.53	51.75	27.43
	149			1.20	51.75	62.10

PREVIEW RO# I 57560 CUST# 10000 MIKE FRAZIER 7130 COMBINE TR  
UNIT# 46268 2012 CASE-IH 7130

\*\*\*\*\* REPAIR ORDER SUMMARY DATA \*\*\*\*\*  
MIKE FRAZIER 7130 COMBINE TR CUST# 10000 RO# 157560  
START 2/03/16 08:00  
BILLED 2/18/16 16:45  
PILOT GROVE IA 52648-0000 PO#  
WRITER 050  
PHONE: HOME 319 469-4461 PHC 12 PBC 01 APPROVAL 050 /050

\*\*\*\*\* REPAIR ORDER TOTALS BY PAY TYPE \*\*\*\*\*  
C PRB 0 I PRB 5 W PRB 0  
BILLED 2/18/16 16:45 050 BILLED  
LABOR 0.00 820.45 0.00  
PARTS 0.00 1,923.55 0.00  
SUBLET 0.00 0.00 0.00  
OTHER 0.00 0.00 0.00  
MISC EXP 0.00 0.00 0.00  
MISC CHARGES 0.00 8.20 0.00  
DEDUCTIBLE 0.00 0.00 0.00  
TAX 0.00 0.00 0.00  
TOTAL DUE 0.00 2,752.20 0.00

\*\*\*\*\* SERVICE UNIT INFORMATION \*\*\*\*\*  
OWNER 10000 UNIT# 46268 2012 CASE-IH 7130 CURR HRS 697.0  
DELIVERED:12/20/13  
VIN: YCG007497  
TIRE SIZE: 900/60/30 RK TR AXLE SN: 2-CAMERAS 7/13  
FEEDER LENGTH: BLKHTR CUT TYPE: AMFMWB  
ROTOR HRS: 531 HR 2-18-16  
WARRANTY EFF: 9/01/12 EXT: N UNIT: YCG007497 EXP: 8/31/13  
ENG: 2CF020021617 EXP: 8/31/14

\*\*\*\*\* PROBLEM # 01 DETAILS \*\*\*\*\*  
PRB# 1 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*  
COMPLAINT: CPO INSPECTION  
TAKE SAMPLES OF:  
ENGINE OIL, COOLANT, HYDRAULIC RESERVOIR AND PTO GEARBOX  
HOLD STATUS: F FINISHED  
OPR# 1 SKILL LEVEL:  
TECH #: 172  
172 1.55 61.50 95.33  
172 1.43 61.50 87.95  
172 1.70 61.50 104.55  
172 1.09 61.50 67.04  
172 .17 61.50 10.46  
PARTS: SG4PACK OIL ANALYS 1.00 124.35 124.35  
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL  
365.33 124.35 0.00 0.00 0.00 489.68

\*\*\*\*\* PROBLEM # 02 DETAILS \*\*\*\*\*  
PRB# 2 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*  
COMPLAINT: FIX LIGHTS, RIGHT TURN SIGNAL BULB, REAR BEACON WILL NOT TURN  
BACK UP ALARM DOES NOT WORK, REPAIR  
HEATED SEAT DOES NOT WORK, REPAIR  
REPLACE SEAL ON AIR BOX  
CORRECTION: BACK UP ALARM--ADJUSTED SWITCH ON THE PROPULSION HANDLE.  
HEATED SEAT--PLUGGED SEAT IN SO IT WOULD HEAT.  
HOLD STATUS: F FINISHED  
OPR# 1 SKILL LEVEL:  
TECH #: 172  
172 .85 61.50 52.28  
PARTS: 84337824 BEACON, RO 1.00 81.25 81.25  
87598111 SEAL, DOOR 1.00 59.00 59.00  
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL  
52.28 140.25 0.00 0.00 0.00 192.53

\*\*\*\*\* PROBLEM # 03 DETAILS \*\*\*\*\*

PRB# 3 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: COVER PLATE ON TRANSMISSION LEAKS, REPAIR  
FIX LEAKING OIL LINES ON LEFT SIDE OF MACHINE  
REPLACE AUX PUMP DRIVE BELT  
STRAIGHTEN LAWNMOWER BLADE BY RADIATOR

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			1.65	61.50	101.48
PARTS:	401885R2	SHIM / TRA		2.00	9.75	19.50
	238-7154	O-RING		1.00	7.60	7.60
	84548651	BELT, JACK		1.00	111.00	111.00
	HYTRAN	OIL / 1 GA		4.50	14.89	67.01
	504218108	TUBE, OIL		2.00	124.20	248.40
	15"	POLY TIE S		4.00	.36	1.44
3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	101.48	454.95	0.00	0.00	0.00	556.43

\*\*\*\*\* PROBLEM # 04 DETAILS \*\*\*\*\*

PRB# 4 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: REPLACE CLEAN GRAIN PADDLE CHAIN  
REPLACE CLEAN GRAIN DRIVE CHAIN

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			1.85	61.50	113.78
	228			2.03	61.50	124.85
PARTS:	84164207	CHAIN, TA		1.00	137.00	137.00
	84163936	CHAIN, CLE		1.00	177.00	177.00
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	238.63	314.00	0.00	0.00	0.00	552.63

\*\*\*\*\* PROBLEM # 05 DETAILS \*\*\*\*\*

PRB# 5 LABOR TYPE 1I INTERNAL WORK \*\* BILLED \*\*

COMPLAINT: REPLACE UNLOADING DRIVE CHAIN  
REPLACE TAILINGS DRIVE CHAIN  
REPLACE ROCK TRAP DRIVE CHAIN

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172

	172			1.02	61.50	62.73
PARTS:	87707588	CHAIN, UNL				0.00
	84250965	CHAIN UNLO		1.00	131.00	131.00
	87365387	CHAIN ASSM		1.00	589.00	589.00
	47667739	CHAIN ROCK		1.00	170.00	170.00
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	62.73	890.00	0.00	0.00	0.00	952.73

\*\*\*\*\* REPAIR ORDER TOTALS \*\*\*\*\*

LABOR SALE	820.45
PARTS SALE	1,923.55
REPAIR ORDER SUBTOTAL	2,744.00
TOTAL MISC. SHOP SUPPLIES	8.20
TOTAL DUE	2,752.20

	149			1.92	51.75	99.36
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	188.89	0.00	0.00	0.00	0.00	188.89

\*\*\*\*\*

REPAIR ORDER TOTALS

\*\*\*\*\*

LABOR SALE	2,550.53
PARTS SALE	887.45
REPAIR ORDER SUBTOTAL	3,437.98
TOTAL MISC. SHOP SUPPLIES	20.59
TOTAL DUE	3,458.57