

PREVIEW RO# I 57479 CUST# 10000 STARR AG 5130 COMBINE TRADE
UNIT# 46363 2013 CASE-IH 5130 NEW C

***** REPAIR ORDER SUMMARY DATA *****
STARR AG 5130 COMBINE TRADE CUST# 10000 RO# I57479

PILOT GROVE IA 52648-0000 START 1/19/16 09:29
PHONE: HOME 319 469-4461 PHC 19 PBC 08 BILLED 5/18/16 14:05
WRITER 024
APPROVAL 024 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 7 W PRB 0
BILLED 5/18/16 14:05 050 BILLED
LABOR 0.00 1,386.19 0.00
PARTS 0.00 1,385.25 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 12.66 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 2,784.10 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46363 2013 CASE-IH 5130 NEW C CURR HRS 588.0
DELIVERED:12/29/14
VIN: YDG009383 ENGINE: 4HF000104708
TIRE SIZE: 470-70R-30 REAR AXLE SN: 30.5L R32 170R1
FEEDER LENGTH: AMFMWB CUT TYPE: BL HTR
ROTOR HRS: 456 HR 12-26-14
WARRANTY EFF: 9/01/13 EXT: N UNIT: YDG009383 EXP: 8/31/14
ENG: 4HF000104708 EXP: 8/31/15

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: SERVICE ENGINE
COMPLETE CHECKLIST AS REQUIRED
CORRECTION: SERVICED ALL FILTERS, CHANGED ENGINE OIL AND HYDRAULIC OIL.
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:

TECH #: 000
026 .75 61.50 46.13
026 1.80 61.50 110.70
026 .90 61.50 55.35
026 1.05 61.50 64.58
026 2.22 61.50 136.53
026 .72 61.50 44.28
026 1.89 61.50 116.24
026 1.60 61.50 98.40
026 .92 61.50 56.58
026 .80 61.50 49.20
026 .09 61.50 5.54
PARTS: 84228488 OIL FILTER 1.00 23.00 23.00
86998333 AIR FILTER 1.00 106.00 106.00
86998332 AIR FILTER 1.00 80.50 80.50
84412164 FILTER, PR 1.00 26.50 26.50
84477370 FUEL FILTE 49.00 0.00
84348882 CARTRIDGE, 1.00 28.00 28.00
1329214C1 HYDRAULIC 1.00 137.00 137.00
120486A2 FILTER / C 1.00 34.75 34.75
84217229 FILTER / C 1.00 51.00 51.00
132096A1 GREASE TUB 10.00 3.75 37.50
73341702 5 GALLON / 1.00 76.00 76.00
HYTRANC 1 GAL / HY 12.50 14.89 186.13
B505500 CHAIN LUBR 1.00 6.04 6.04
UPS OUT 1.00 8.66 8.66
1 LABOR 783.53 PARTS 801.08 SUBLET 0.00 OTHER 0.00 MISC 0.00 PROB TOTAL 1584.61

***** PROBLEM # 02 DETAILS *****
 PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: ROCK TRAP CHAIN
 CORRECTION: REPLACED ROCK TRAP CHAIN.
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #: 000
 026 .65 61.50 39.98
 026 .09 61.50 5.54
 PARTS: 47667739 CHAIN ROCK 1.00 170.00 170.00
 2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 45.52 170.00 0.00 0.00 0.00 215.52

***** PROBLEM # 03 DETAILS *****
 PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: UNLOADING DRIVE CHAIN
 ELEVATOR DRIVE CHAIN
 CORRECTION: REPLACED UNLOADING AUGER DRIVE CHAIN.
 REPLACED ELEVATOR DRIVE CHAIN, ADJUSTED ELEVATOR
 CLEAN GRAIN CHAIN. OILED CHAINS. CHECKED BELTS FOR TENSION.
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #: 026
 026 1.45 61.50 89.18
 026 1.77 61.50 108.86
 026 1.34 61.50 82.41
 026 .09 61.50 5.54
 PARTS: 87707588 CHAIN, UNL 1.00 159.00 159.00
 84163936 CHAIN, CLE 1.00 177.00 177.00
 3 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 285.99 336.00 0.00 0.00 0.00 621.99

***** PROBLEM # 04 DETAILS *****
 PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: AIR CLEANER HONEYCOMB PLUGGED
 CAB AIR CLEANER SUPPLY PLUGGED
 CORRECTION: TOOK AIR CLEANER BOX OFF, HONEYCOMB WAS PLUGGED UP, TOOK CAB
 FILTER OUT, CLEANED UP HOUSING--IT WAS PLUGGED.
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #: 026
 026 1.31 61.50 80.57
 026 .07 61.50 4.31
 4 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 84.88 0.00 0.00 0.00 0.00 84.88

***** PROBLEM # 05 DETAILS *****
 PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: CHANGE PTO GEARBOX OIL
 CORRECTION: CHANGED PTO GEAR BOX OIL
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #: 026
 228 1.08 61.50 66.42
 PARTS: HYTRAN OIL / 1 GA 5.25 14.89 78.17
 5 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 66.42 78.17 0.00 0.00 0.00 144.59

***** PROBLEM # 06 DETAILS *****
 PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT:
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #: 228
 6 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
 0.00 0.00 0.00 0.00 0.00 0.00

***** PROBLEM # 07 DETAILS *****

PRB# 7 LABOR TYPE 11 INTERNAL WORK ** BILLED **

COMPLAINT: JOSH WORKED ON CPO WO 57608 PROB 2 5-10-16---CPO WO HAS
ALREADY BEEN CLOSED

CORRECTION: INSTALLED STEERING COLUMN. TOOK MONITOR TO PARTS. TEST RAN
AND PARKED OUTSIDE.

HOLD STATUS: F FINISHED
OPR# 1

SKILL LEVEL:

TECH #: 228
172

7	LABOR	PARTS	SUBLET	OTHER	1.88	MISC	63.75	PROB TOTAL	119.85
	119.85	0.00	0.00	0.00		0.00			119.85

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,386.19
PARTS SALE	1,385.25
REPAIR ORDER SUBTOTAL	2,771.44
TOTAL MISC. SHOP SUPPLIES	12.66
TOTAL DUE	2,784.10

PREVIEW RO# I 57608 CUST# 10000 STARR AG 5130 COMBINE TRADE
UNIT# 46363 2013 CASE-IH 5130 NEW C

***** REPAIR ORDER SUMMARY DATA *****
STARR AG 5130 COMBINE TRADE CUST# 10000 RO# I57608
START 2/09/16 09:29
BILLED 5/10/16 14:33
PILOT GROVE IA 52648-0000 PO#
WRITER 050
PHONE: HOME 319 469-4461 PHC 09 PBC 03 APPROVAL 050 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 7 W PRB 0
BILLED 5/10/16 14:33 050 BILLED
LABOR 0.00 1,411.68 0.00
PARTS 0.00 1,047.33 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 14.12 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 2,473.13 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46363 2013 CASE-IH 5130 NEW C CURR HRS 588.0
DELIVERED: 12/29/14
VIN: YDG009383 ENGINE: 4HF000104708
TIRE SIZE: 470-70R-30 REAR AXLE SN: 30.5L R32 170R1
FEEDER LENGTH: AMFMWB CUT TYPE: BL HTR
ROTOR HRS: 456 HR 12-26-14
WARRANTY EFF: 9/01/13 EXT: N UNIT: YDG009383 EXP: 8/31/14
ENG: 4HF000104708 EXP: 8/31/15

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CPO INSPECTION
TAKE SAMPLES OF:
ENGINE OIL, COOLANT, HYDRAULIC RESERVOIR AND PTO GEARBOX
CORRECTION: JOSH DID CPO INSPECTION 2-29-16 AND 3-1-16
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
172 1.35 61.50 83.03
172 1.67 61.50 102.71
172 2.57 63.75 163.84
172 1.45 63.75 92.44
PARTS: SG4PACK OIL ANALYS 1.00 124.35 124.35
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
442.02 124.35 0.00 0.00 0.00 566.37

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: REPAIR LEFT REAR TAIL LIGHT
REPAIR DOME LIGHT
REPAIR REAR BEACON
REPAIR FRONT BEACON
CORRECTION: REPLACED BULB ON LEFT REAR TAIL LIGHT.
REPLACED BULB ON DOME LIGHT.
REPLACED BULB ON REAR BEACON.
REPLACED BEACON ON FRONT RIGHT.
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
172 1.10 63.75 70.13
172 .75 63.75 47.81
172 .25 63.75 15.94
PARTS: 87627854 LIGHT ASSY 1.00 19.25 19.25
86616249 BULB / HEA 1.00 3.15 3.15

	47691331		BULB, BEAC	1.00	10.50	10.50
	47670938		BEACON ROT	1.00	93.75	93.75
2	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	133.88	126.65	0.00	0.00	0.00	260.53

***** PROBLEM # 03 DETAILS *****

PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: OIL COOLER LEAK BY HOSE CLAMP
 CORRECTION: TIGHTENED HOSE CLAMP UP ON LOWER COOLER HOSE.
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172
 172 .22 63.75 14.03
 172 .92 63.75 58.65

3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	72.68	0.00	0.00	0.00	0.00	72.68

***** PROBLEM # 04 DETAILS *****

PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: JACKSHAFT BEARING SPUN FOR HYDRO AND UNLOADING DRIVE
 CORRECTION: TOOK OLD SHAFT OUT AND REPLACED SHAFT, BEARINGS, LOCK
 COLLARS AND OUTER PULLEY.
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172
 172 1.60 63.75 102.00
 172 .63 63.75 40.16
 172 1.40 63.75 89.25
 172 1.25 63.75 79.69
 172 1.08 63.75 68.85
 172 1.49 63.75 94.99

PARTS:	84057307	BEARING, B	2.00	62.00	124.00
	563733	COLLAR, LO	2.00	15.00	30.00
	354775	KEY, M10X4	2.00	4.00	8.00
	86620027	FLANGE	4.00	12.00	48.00
	84152427	HALF SHAFT	1.00	121.00	121.00
	84152415	PULLEY, DO	1.00	260.00	260.00

OTHER:	SPO ON 16380				0.00	
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	474.94	591.00	0.00	0.00	0.00	1065.94

***** PROBLEM # 05 DETAILS *****

PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: TAILINGS DRIVE CHAIN NEEDS REPLACED
 SPREADER CURTAIN LATCH MISSING
 CORRECTION: REPLACED TAILING SDRIVE CHAIN.
 INSTALLED MISSING LATCH ON SPREADER CURTAIN.
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172
 172 1.05 63.75 66.94
 172 .32 63.75 20.40
 172 1.10 63.75 70.13
 PARTS: 84164207 CHAIN, TA 1.00 137.00 137.00
 87702314 PIN ASSY, 1.00 28.00 28.00
 87364 WASHER / 1 2.00 .41 0.82
 86512497 NUT, LOCK, 1.00 2.41 2.41

5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	157.47	168.23	0.00	0.00	0.00	325.70

***** PROBLEM # 06 DETAILS *****

PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: LOOSE BEARING IN ROTARY SCREEN BLADE
 CORRECTION: REPLACED BEARINGS ON UPPER ROTARY AIR SCREEN CLEANING BLADE.
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 172
 172 .95 63.75 60.56

PARTS:	SNAP		RING	1.00	.95	0.95
	308803		BEARING /	2.00	12.00	24.00
	1302758C1		PLUG / 2-7	1.00	4.35	4.35
6	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	60.56	29.30	0.00	0.00	0.00	89.86

***** PROBLEM # 07 DETAILS *****

PRB# 7 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: KEYSTOCK GRATE MISSING BOLT
 REPAIR FEEDER CHAIN CONNECTOR LINK
 CORRECTION: INSTALLED MISSING BOLT ON KEYSTOCK GRATES.
 INSTALLED NEW KEEPER ON CONNECTING LINK ON FEEDER CHAIN.

HOLD STATUS: F FINISHED
 OPR# 1

SKILL LEVEL:

TECH #: 172

	172			1.10	63.75	70.13
PARTS:	86981484		BOLT - 10M	2.00	2.70	5.40
	P2840-010		NUT - 10MM	2.00	1.20	2.40
7	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	70.13	7.80	0.00	0.00	0.00	77.93

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,411.68
PARTS SALE	1,047.33
REPAIR ORDER SUBTOTAL	2,459.01
TOTAL MISC. SHOP SUPPLIES	14.12
TOTAL DUE	2,473.13