

PREVIEW RO# I 57566 CUST# 10000 QUINN AG ENT 7230 COMB TRADE
UNIT# 46444 2013 CASE-IH 7230 COMBI

***** REPAIR ORDER SUMMARY DATA *****
QUINN AG ENT 7230 COMB TRADE CUST# 10000 RO# I57566

PILOT GROVE IA 52648-0000 START 2/03/16 10:36
BILLED 2/25/16 15:26
PHONE: HOME 319 469-4461 PHC 10 PBC 03 PO#
WRITER 050
APPROVAL 050 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 6 W PRB 0
BILLED BILLED 2/25/16 15:26 050 BILLED
LABOR 0.00 1,163.00 0.00
PARTS 0.00 8,164.87 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 11.63 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 9,339.50 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46444 2013 CASE-IH 7230 COMBI CURR HRS 853.0
DELIVERED:12/15/15
VIN: YDG219493 ENGINE: 2CF01603065
TIRE SIZE: 520/85R42 DUALS AXLE SN: 540/65R30 R1W
FEEDER LENGTH: AMFMWB CUT TYPE: BLK HT
ROTOR HRS: 563 HRS 12-7-15
WARRANTY EFF: EXT: N UNIT: YDG219493 EXP: 8/31/14
ENG: 2CF016030655 EXP: 8/31/15

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CPO INSPECTION
TAKE SAMPLES OF:
ENGINE OIL, COOLANT, HYDRAULIC RESERVOIR AND PTO GEARBOX.
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
172 .63 61.50 38.75
172 2.58 61.50 158.67
172 2.12 61.50 130.38
172 1.42 61.50 87.33
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
415.13 0.00 0.00 0.00 0.00 415.13

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: FIX LIGHTS, LEFT REAR AFTER CUT, RIGHT FRONT BEACON, REAR
BEACON
BOTH FINAL DRIVE COVERS LEAKING, FIX
REPLACE WEATHER STRIPPING LEFT SIDE OF GRAIN TANK
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 172
PARTS: 172 1.27 61.50 78.11
42570987 LIGHT ASSY 1.00 5.32 5.32
47691331 BULB, BEAC 1.00 9.45 9.45
ATO FUSE / SPA 1.00 1.16 1.16
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
78.11 15.93 0.00 0.00 0.00 94.04

***** PROBLEM # 03 DETAILS *****
PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: REPLACE FEEDER CHAIN AND WEAR STRIPS
REPLACE FEEDER DRIVE SPROCKETS AND BRGS.

REPLACE SHAFT IN GEAR BOX THAT DRIVES SPROCKETS
 REPLACE BOIL UP AUGER

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 172

	172		.93	61.50		57.20
	172		2.55	61.50		156.83
	172		2.00	61.50		123.00
	172		.03	61.50		1.85
PARTS:	86638209	WEAR STRIP	4.00	23.00		92.00
	84179639	FEEDER CHA	1.00	1596.60		1,596.60
	47778344	KIT, SPROC	1.00	2047.50		2,047.50
	86995212	BEARING-FE	2.00	114.30		228.60
	87282003	SHAFT-GEAR	1.00	576.00		576.00
	87282006	GUARD/GEAR	1.00	14.40		14.40
	87612665	SEAL/FEEDE	1.00	25.65		25.65
	84415750	SEAL, GREA	1.00	6.26		6.26
	84257096	LINK, CONN	4.00	24.75		99.00
	87612665	SEAL/FEEDE	1.00	25.65		25.65
	P2841-130	CARR. BOLT	1.00	.94		0.94
	140045	WASHER / 1	1.00	.49		0.49
	BOLT5	METRIC BOL	.50	1.48		0.74
	87280254	BUSHING, F	2.00	20.70		41.40
	7"	POLY TIE S	8.00	.13		1.04
	14"	POLY TIE S	3.00	.23		0.69
	87682392	BOLT, CARR	3.00	3.20		9.60
	84414985	BEARING, F	2.00	5.58		11.16
	535318	BUSHING, P	1.00	14.63		14.63
	87733275	AUGER, INC	1.00	990.00		990.00
3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	338.88	5782.35	0.00	0.00	0.00	6121.23

***** PROBLEM # 04 DETAILS *****
 PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: REPLACE FRONT HALF RASP BARS ON ROTOR
 TURN SOME ROTORY CHOPPER KNIVES
 WELD SPREADER FINS, THEY ARE CRACKED

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 172

	172		2.13	61.50		131.00
PARTS:	B95365	1/2 KIT /	1.00	778.50		778.50
	P2838-201	BOLT / M12	40.00	.72		28.80
	87605590	BEARING AS	1.00	39.60		39.60
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	131.00	846.90	0.00	0.00	0.00	977.90

***** PROBLEM # 05 DETAILS *****
 PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: REPLACE CLEAN GRAIN PADDLE CHAIN AND BOTH SPROCKETS
 REPLACE BOTH CLEAN GRAIN DRIVE CHAINS
 ELEVATOR SLIP CLUTCH LOOSE ON SHAFT, REPAIR
 REPLACE TAILINGS PROCESSOR BELT

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 172

	172		2.75	61.50		169.13
PARTS:	47429223	CHAIN, ELE	1.00	700.20		700.20
	87283438	SPROCKET /	1.00	106.20		106.20
	87283436	SPROCKET,	1.00	104.40		104.40
	87470736	CHAIN INCL	1.00	55.58		55.58
	87470737	CHAIN, CLE	1.00	87.08		87.08
	87605593	BEARING CL	1.00	73.35		73.35
	87605590	BEARING AS	2.00	39.60		79.20
	87607871	BELT ROTAR	1.00	21.60		21.60
	87476486	BELT / ELE				0.00
	87283139	BELT-TAILI	1.00	79.65		79.65
	47691331	BULB, BEAC	1.00	9.45		9.45
	9804278	NUT, M10 F	3.00	2.12		6.36

	9993141		O-RING	2.00	.68	1.36
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	169.13	1324.43	0.00	0.00	0.00	1493.56

 PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: REPLACE UNLOADING DRIVE CHAIN
 RE-ROUTE COOLANT RESERVOIR VENT HOSE
 REPLACE BELT OFF OF ENGINE THAT DRIVES AIR SCREEN
 INSTALL TWO RETAINING PINS ON PLASTIC COVER ON TAILINGS BELT

HOLD STATUS: F FINISHED
 OPR# 1

SKILL LEVEL:

TECH #: 172

	172			.50	61.50	30.75
PARTS:	84566255		CHAIN, STD	1.00	194.40	194.40
	87299408		LYNCH PIN	2.00	.43	0.86
6	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	30.75	195.26	0.00	0.00	0.00	226.01

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,163.00
PARTS SALE	8,164.87
REPAIR ORDER SUBTOTAL	9,327.87
TOTAL 'MISC. SHOP SUPPLIES	11.63
TOTAL DUE	9,339.50

PREVJ W RO# I 57244 CUST# 10000 QUINN AG ENTERPRISE 7230 TRAD
UNIT# 46444 2013 CASE-IH 7230 COMBI

***** REPAIR ORDER SUMMARY DATA *****
QUINN AG ENTERPRISE 7230 TRADE CUST# 10000 RO# I57244

PILOT GROVE IA 52648-0000 START 12/14/15 15:05
PHONE: HOME 319 469-4461 PHC 15 PBC 04 BILLED 2/25/16 11:39
WRITER 175
APPROVAL 175 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 6 W PRB 0
BILLED 2/25/16 11:39 050 BILLED
LABOR 0.00 1,386.31 0.00
PARTS 0.00 1,421.71 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 5.66 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 2,813.68 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46444 2013 CASE-IH 7230 COMBI CURR HRS 853.0
DELIVERED:12/15/15
VIN: YDG219493 ENGINE: 2CF01603065
TIRE SIZE: 520/85R42 DUALS AXLE SN: 540/65R30 R1W
FEEDER LENGTH: AMFMWB CUT TYPE: BLK HT
ROTOR HRS: 563 HRS 12-7-15
WARRANTY EFF: EXT: N UNIT: YDG219493 EXP: 8/31/14
ENG: 2CF016030655 EXP: 8/31/15

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (FLAGSHIP)-RECONDITIONING INSPECTION.
PERFORM THE FLAGSHIP COMBINE RECONDITIONING INSPECTION.
PER THE FLAGSHIP COMBINE RECONDITIONING INSPECTION CHECK
LIST.
HOLD STATUS: F FINISHED
OPR# 1 I.COMINFLRIC00 ----- FLAT RATE SKILL LEVEL:
INT. COMBINE (FLAGSHIP)-RECONDITIONING INSP
TECH #: 041
041 .93 0.00
041 2.47 0.00
041 1.03 0.00
139 .66 0.00
225 1.47 0.00
225 1.23 0.00
225 2.82 0.00
225 1.97 0.00
LABOR: 4.00 82.00 328.00
PARTS: UPS OUT 1.00 8.66 8.66
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
328.00 8.66 0.00 0.00 0.00 336.66

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CHARLIE PICKED UP 12-11-15
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 000
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
0.00 0.00 0.00 0.00 0.00 0.00

***** PROBLEM # 03 DETAILS *****
PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (FLAGSHIP)-RECONDITIONING SERVICE
PHIL AND MIKE ARE DOING SOME OF THE PROBLEMS ON THE CPO

INSPECTION

CORRECTION: PERFORM THE STEPS OUTLINED ON THE FORM TITLED "COMBINE
SERVICING CHECK LIST FOR FLAGSHIP COMBINES"

NEED TO CHANGE THE OIL IN THE PTO GEARBOX

HOLD STATUS: F FINISHED

OPR# 1 I.COMSEFLRSC00 ----- FLAT RATE SKILL LEVEL:
INT. COMBINE (FLAGSHIP)-RECONDITIONING SERV

TECH #: 228

225	1.82	0.00
225	.66	0.00
225	1.02	0.00
225	.03	0.00
225	2.68	0.00
225	1.25	0.00
225	2.93	0.00
225	1.75	0.00
225	2.65	0.00
225	1.25	0.00
225	2.82	0.00
228	2.58	0.00
228	.85	0.00
228	1.52	0.00
228	2.10	0.00
228	1.67	0.00
228	1.47	0.00
228	1.95	0.00
228	1.03	0.00
228	2.57	0.00
228	2.07	0.00
228	3.88	0.00
228	2.65	0.00
228	2.30	0.00
228	1.78	0.00
228	1.73	0.00
228	2.60	0.00
228	1.25	0.00
228	.20	0.00
228	.78	0.00

LABOR:			6.00	82.00	492.00
PARTS:	84487937	FILTER / H	1.00	103.00	103.00
	84523925	HYDRALIC F	1.00	52.50	52.50
	254353A1	HYD. FILTE	1.00	116.00	116.00
	84346773	OIL FILTER	1.00	54.75	54.75
	HYTRAN	OIL / 1 GA	14.25	14.89	212.18
	15W40D	1 GALLON /	8.75	14.75	129.06
	SG4PACK	OIL ANALYS	1.00	124.35	124.35
	HYTRAN	OIL / 1 GA	2.75	14.89	40.95
	84597064	FILTER, FU	1.00	45.00	45.00
	84348882	CARTRIDGE,	1.00	28.00	28.00
	84305935	FILTER, IN	1.00	98.75	98.75
	84305930	FILTER, OU	1.00	143.00	143.00
	360260A2	FILTER, CA	1.00	67.75	67.75
	84217229	FILTER / C	1.00	51.00	51.00
	87414	GREASE ZER	1.00	.99	0.99
	B30205	ANTIFREEZE	1.00	33.88	33.88
	GEARLUBE	OIL / 1 GA	4.00	18.80	75.20

3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	492.00	1376.36	0.00	0.00	0.00	1868.36

***** PROBLEM # 04 DETAILS *****

PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: CLEAN UP AND TAKE PICTURES FOR TRACTOR HOUSE

CORRECTION: DAVE AND KENNY CLEANED OUT THE GRAIN TANK 12-16-15

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 149

138	1.94	61.50	119.31
149	2.15	51.75	111.26
149	1.15	51.75	59.51
149	2.60	51.75	134.55
149	.92	51.75	47.61

PARTS:	B17566N		SPRAY PAIN	2.00	9.95	19.90
	990121N		SPRAY PAIN	1.00	9.95	9.95
	ZRG018GLC		GLASS CLEA	1.00	3.70	3.70
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	472.24	33.55	0.00	0.00	0.00	505.79

***** PROBLEM # 05 DETAILS *****

PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: GRAIN TANK WOULD NOT UNFOLD

CORRECTION: GERMAIN ADJUSTED SENSOR FOR UNFOLD.

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #:	138					
	174				.20	61.50 12.30
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	12.30	0.00	0.00	0.00	0.00	12.30

***** PROBLEM # 06 DETAILS *****

PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: CLEAN AND DETAIL

HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #:	174					
	149				1.58	51.75 81.77
PARTS:	W8418		ARMORALL C	1.00	3.14	3.14
6	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	81.77	3.14	0.00	0.00	0.00	84.91

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,386.31
PARTS SALE	1,421.71
REPAIR ORDER SUBTOTAL	2,808.02
TOTAL MISC. SHOP SUPPLIES	5.66
TOTAL DUE	2,813.68